ComplyOnSite
complyonsite.com

Scaffold inspection report

No. SI-171126-0805
Tag S-014
Your ref Job 2291

Site	14 Mill Lane, Leeds LS6 2AB
Scaffold, type and duty	Front elevation, lifts 1 to 3
Inspected	Tue 17 Nov 2026, 08:05
Why	Weekly
Carried out for	Cole Build Ltd, Unit 2, Kirkstall Road, Leeds LS4 2AZ

CONCLUSION **Safe to use**

INSPECTED BY Priya Shah, Site manager, Cole Build Ltd

Defects and action

1. **Guardrails, toe boards and brick guards. East end, lift 2. End guardrail missing**
   Found at SI-101126-0810, Tue 10 Nov, 08:10. Today: Put right

Action taken: Guardrail refitted by Price Scaffolding, lift 2 reopened

Since the last inspection

SI-101126-0810, Tue 10 Nov, 08:10, by Priya Shah, Site manager. Conclusion then: Safe to use with restrictions. Lift 2 not to be used until the end guardrail is refitted..

Guardrails, toe boards and brick guards: Defect last time, OK today.

Earlier defect: 1 put right.

Checks

	Today	Last		Today	Last
Base plates, sole boards and ground	OK	OK	Ladders, stairs and access	OK	OK
Tubes, bracing and couplers	OK	OK	Materials, within its load class	OK	OK
Ties and anchors	OK	OK	Sheeting and netting	OK	OK
Platforms and boards	OK	OK	Surroundings, power lines and vehicles	OK	OK
Guardrails, toe boards and brick guards	OK	Defect	Signs and tag	OK	OK

Inspected by



Priya Shah, Site manager
Cole Build Ltd, card CISRS 7654321
Signed Tue 17 Nov 2026, 08:24

Seen by

For Cole Build Ltd
Not signed

The particulars of an inspection report in Schedule 7 of the Work at Height Regulations 2005, Schedule 8 in Northern Ireland.