ComplyOnSite
complyonsite.com

Scaffold handover certificate

No. SH-031126-1540
Tag S-014
Your ref Job 2291

Site	14 Mill Lane, Leeds LS6 2AB
Scaffold or section	Front elevation, lifts 1 to 3
Handover of	New scaffold
Type	Independent tied
Boarded lifts	3 boarded lifts
Handed over	Tue 3 Nov 2026, 15:40

FOR USE IN	**Brickwork to the front elevation**
LOADING	**General purpose, 2.0 kN/m². 2 lifts at a time**
RESTRICTIONS	**Do not load the top lift.** **Do not remove ties, boards or guardrails. Ask the scaffolder.**
SCAFFOLDER	**Price Scaffolding Ltd, 07700 900123**

Built to	TG20 compliance sheet, ref 48213 rev A
Ties	Tied, tested, test ref PT-17, 6 ties at 6.1 kN
Sheeting or netting	Debris netting
Checked before handover	Base plates and sole boards, Standards, ledgers and bracing, Ties, Boards, Guardrails and toe boards, Ladders and access, Signs and tag

Inspection before first use

Inspected	Tue 3 Nov 2026, 15:40
Inspected by	Dan Price, Supervisor, Price Scaffolding Ltd
Carried out for	Cole Build Ltd, Unit 2, Kirkstall Road, Leeds LS4 2AZ
Anything that could give rise to a risk	None found.
Action taken	None needed.
Further action needed	Inspect before use every 7 days and after bad weather or any change.

The particulars of an inspection report in Schedule 7 of the Work at Height Regulations 2005 (Schedule 8 in Northern Ireland).

Handed over by



Dan Price
Price Scaffolding Ltd
Supervisor
Card CISRS 1234567
Signed Tue 3 Nov 2026, 15:41

Received by



Sarah Cole
Cole Build Ltd
Site manager
Signed Tue 3 Nov 2026, 15:44

Inspect it after anything that could affect it. Where someone could fall 2 metres or more, inspect it again within 7 days too.