ComplyOnSite
complyonsite.com

Mobile tower inspection report

No. TI-121126-0745
Tag T-03

Site	Oakfield Primary School, Leeds LS8 1QT
Tower and where it stands	Main hall, east wall
Make, model and instructions	Aluminium tower, 1.45 m by 2.5 m, maker's manual issue 4
Platform height	4.2 m
Inspected	Thu 12 Nov 2026, 07:45
Why	After building it, before first use
Carried out for	Oakfield Primary School, Oak Road, Leeds LS8 1QT

CONCLUSION **Safe to use. Platform at 4.2 m. Use it in this position. Move it only as the maker's instructions say, with nobody and nothing on it.**

INSPECTED BY Jo Hart, Site manager, Oakfield Primary School

Defects and action

1. Castors, brakes or base plates. North west castor. Brake not holding when pushed

Action taken	Castor replaced from spares and brake tested
Today	Put right

Checks

	Today		Today
Castors, brakes or base plates	OK	Guardrails and toe boards	OK
Adjustable legs and level	OK	Ladders and internal access	OK
Stabilisers or outriggers	OK	Built to the maker's instructions	OK
Frames, locks and clips	OK	Ground, wind and surroundings	OK
Braces	OK	Tag or label	OK
Platforms and trapdoors	OK		

Inspected by



Jo Hart, Site manager
Oakfield Primary School, card PASMA 112233
Signed Thu 12 Nov 2026, 08:05

Seen by

For Oakfield Primary School
Not signed

The particulars of an inspection report in Schedule 7 of the Work at Height Regulations 2005, Schedule 8 in Northern Ireland.